

LOCAL NOTICE TO MARINERS

U.S. Department of Homeland Security

United States Coast Guard



WEEKLY EDITION – JULY 2003

~Navigation Information Service (NIS)~ Watchstander, 24 hours a day at (703) 313-5900 ~Navcen Internet Address~ www.navcen.uscq.gov ~Local Notice to Mariners~ www.navcen.uscg.gov/lnm

Commander (oan) Issued by:

Seventeenth Coast Guard District

PO Box 25517

Juneau. AK 99802-5517

(907) 463-2269 (0800-1600) Telephone: After Hours: (907) 463-2004 (1600-0800)

Facsimile: (907) 463-2273

E-mail: Inm@cgalaska.uscg.mil

Questions, comments or additional information on this Local Notice to Mariners or the Local Notice to Mariners mailing list (additions, deletions, corrections) should be sent to the address above or by E-mail to: Inm@cgalaska.uscg.mil For faster service, you can get the U.S. Coast Guard 17th District's Local Notice to Mariners via the Internet directly from the U.S. Coast Guard Navigation Center web site at www.nis-mirror.com/default.html or to get on our electronic mailing list and receive a Microsoft Word copy of the Local Notice to Mariners, send requests to the standard mail address above or by E-mail.

REFERENCES: Light List, Vol. VI. Pacific Coast and Pacific Islands, 2002 Edition (COMDTPUB P16502.6).

U.S. Coast Pilot 8, Pacific Coast Alaska: Dixon Entrance to Cape Spencer, 24th Edition.

U.S. Coast Pilot 9, Pacific and Arctic Coasts Alaska: Cape Spencer to Beaufort Sea, 20th Edition.

BROADCAST NOTICE TO MARINERS

Navigation information previously promulgated by Broadcast Notice to Mariners 019/03 through 190/03 and still in effect is included in this notice.

USE OF THE LOCAL NOTICE TO MARINERS

The Weekly Supplemental editions contain new information available subsequent to the issue of the Monthly edition. To ensure having complete information concerning the waterways of the Seventeenth Coast Guard District, consult previous Monthly editions dated for the first Tuesday of each month.

I SPECIAL NOTICES

The Dates of Latest Editions, Nautical Charts and Miscellaneous Maps, dated July 1, 2003, published by the National Ocean Service, is available for issue. It may be obtained free by mail from the National Aeronautical Charting Office, AVN-530, Federal Aviation Administration, 6303 lvy Lane, Suite 400, Greenbelt MD, 20770-1479, by telephone at 1-800-638-8972 or from your local authorized nautical chart sales agent. This is a quarterly publication listing the most recent editions of nautical charts, miscellaneous maps and publications relating to navigation, weather, etc. with brief descriptions and up-to-date prices for most of the publications listed.

THE U.S. COAST GUARD NAVIGATION CENTER WEB SITE

The primary NAVCEN web site is down due to technical difficulties until further notice. We regret any inconvenience you may have experienced during our technical difficulties. We assure you every effort is being made to return the full array of services provided by the NAVCEN. In an effort to better assist you, the NAVCEN secondary web site can be found here: www.nis-mirror.com/default.html. We recommend you bookmark this location until further notice. The Navigation Information Service 24-hour help desk is available and you can contact them at (703) 313-5900 or E-mail: NISWS@navcen.uscq.gov.

BRIDGE-TO-BRIDGE RADIOTELEPHONE LISTENING WATCH

VHF radio equipment used to meet the U.S. Bridge-to-Bridge Radiotelephone Act requirement for maintaining a listening watch on the vessel bridge-tobridge navigation channel 13, must be capable of a continuous, uninterrupted watch. Any radio equipment capable of disrupting the channel 13 watch by a distress call on channel 16 or a distress call on the Global Maritime Distress & Safety System digital selective calling channel 70, should either not be used or have that disruption feature disabled.

AVAILABILITY OF A NATIONAL OCEAN SERVICE CRITICAL CHART CORRECTIONS WEB SITE

The Office of Coast Survey, National Ocean Service (NOS), NOAA, announces a new Internet service to the marine public at the following web site: http://chartmaker.ncd.noaa.gov This service provides advance notification of critical chart corrections identified by NOS cartographers during nautical chart updating activities. Critical chart corrections are either recently identified hazards to navigation or are information regarded by NOS as essential for safe navigation, e.g. channel conditions, bridge and cable clearances, regulatory changes. Critical chart corrections posted on this web site are forwarded to the United States Coast Guard (USCG) and the National Imagery and Mapping Agency (NIMA) for inclusion in their Local Notice To Mariners (LNM) and Notice To Mariners (NM) respectively. Additionally, updates to the United States Coast Pilot, Volumes 1-9, are posted on this web site. This web site must not be viewed as a substitute for either the USCG LNM or the NIMA NM. Aid to navigation changes and other important information published in USCG and NIMA notices are not available on this web site.

REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

Date 29 JULY 2003 PAGE 1

COMMANDER 17TH COAST GUARD DISTRICT

I SPECIAL NOTICES (CONT.)

DEPARTMENT OF HOMELAND SECURITY - REPORTING SUSPICIOUS ACTIVITY

The Department of Homeland Security (DHS) encourages the maritime public to report information concerning suspicious activity to their local Federal Bureau of Investigation (FBI) Joint Terrorism Task Force (JTTF) office, www.fbi.gov/contact/fo/fo.htm, the DHS Watch and Warning Unit at (202) 323-3205, toll free at 1-888-585-9078, or by E-mail to nipc.watch@fbi.gov, to any Coast Guard unit or other appropriate authorities. The Coast Guard reminds the maritime industry that they may also report suspicious activity to the National Response Center (NRC) at 1-800-424-8802.

AK - INSTRUMENT MOORING NOTICE

NOAA's National Ocean Service installed eight current meters in northern Cook Inlet, Alaska. All were deployed between Point Possession and Knik Arm. These meters use an acoustic frequency of 300 kHz to measure the water currents and are incorporated into taut line subsurface mooring systems which are anchored to the bottom and extend about 22 feet above the bottom. These systems will remain in the locations noted below until approximately August 18, 2003.

Three current meters were installed on 14 July in a north/south line starting just northwest of Pt. Possession and ending south of the Susitna River delta. They were deployed at the following locations:

61°09.65'N 150°33.90'W Instrument is 56 feet below the surface 61°06.82'N 150°33.69'W Instrument is 51 feet below the surface 61°03.37'N 150°33.49'W Instrument is 60 feet below the surface

One station was deployed south of Point Mackenzie at the following location:

61°13.92'N 149°58.57'W Instrument is 26 feet below the surface

On July 15, four stations were installed north of the Port of Anchorage in the Cairn Point/Port Mackenzie area. They were deployed at the following locations:

61°16.69'N 149°53.67'W Instrument is 40 feet below the surface 10°16.48'N 149°52.93'W Instrument is 47 feet below the surface 10°15.14'N 149°55.24'W Instrument is 26 feet below the surface 10°15.85'N 149°53.83'W Instrument is 120 feet below the surface

LEVEL ISLAND - DGPS OFF AIR

Level Island DGPS site will be off air for maintenance during the following time period: Primary: 1800Z – 2000Z 26 August 2003

Alternate: 1800Z – 2000Z 04 September 2003

ANNETTE ISLAND - DGPS OFF AIR

Annette Island DGPS site will be off air for maintenance during the following time period: Primary: 1800Z – 2000Z 02 September 2003

Alternate: 1800Z – 2000Z 08 September 2003

II DISCREPANCIES - DISCREPANCIES CORRECTED

WARNING: Mariners are cautioned that portions of destroyed structures may remain visible or may be submerged.

Abbreviations normally used in the Local Notice to Mariners are as follows: BNM – Broadcast Notice to Mariners

LNM – Local Notice to Mariners

TRLB – Temporarily Replaced by Lighted Buoy

TLB – Temporarily Replaced by Unlighted Buoy

TRUB – Temporarily Replaced by Unlighted Buoy

TDBN – Temporary Daybeacon

TUB – Temporary Unlighted Buoy

DISCREPANCIES

DISCILLIF	NICIES						
LLNR	NAME OF AID	STATUS	CHART	BNM	LNM		
NONE							
DISCREPANCIES/PRIVATE AIDS							
LLNR	NAME OF AID	STATUS	CHART	BNM	LNM		
24754	East Edna Bay Log Breakwater Lights (3)	Missing		019-03	04/03		
24752	Edna Bay Shoal Buoys (10)	Missing		020-03	04/03		
DISCREPA	NCIES CORRECTED						
LLNR	NAME OF AID	STATUS	CHART	BNM	LNM		
NONE							

III <u>TEMPORARY CHANGES – TEMPORARY CHANGES COR</u>RECTED

TEMPORARY CHANGES

	STATUS	CHART	BNM	LNM					
Port Chatham Shoal Daybeacon "PC"	Daybeacon has been temporarily replaced with a	16645	159-02	19/02					
	Junction Buoy			<u> </u>					
Wrangell Narrows Light 56	Temporarily replaced with a lighted buoy	17375	190-03	30/03					
TEMPORARY CHANGES CORRECTED									
NAME OF AID	STATUS	CHART	BNM	LNM					
Point Bentinck Light	Commissioned	16709	096/03	29/03					
'	Wrangell Narrows Light 56 Y CHANGES CORRECTED NAME OF AID	Junction Buoy Wrangell Narrows Light 56 Temporarily replaced with a lighted buoy Y CHANGES CORRECTED NAME OF AID STATUS	Junction Buoy Wrangell Narrows Light 56 Temporarily replaced with a lighted buoy 17375 Y CHANGES CORRECTED NAME OF AID STATUS CHART	Junction Buoy Wrangell Narrows Light 56 Y CHANGES CORRECTED NAME OF AID Junction Buoy Temporarily replaced with a lighted buoy 17375 190-03 CHART BNM					

REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

IV CHART CORRECTIONS

Date 29 JULY 2003 PAGE 2

17360 33rd Ed May 01 2003 Last LNM: 29/03 AK-SOUTHEAST COAST-ETOLIN ISLAND TO MIDWAY IS Relocate Coffman Cove Entrance Light FI W 2.5s 40ft 5M	NAD83 SLANDS INCLUDING	(CGD17) G SUMNER STRAIT at to	56°01'02.6"N 132°49'38.3"W 56°01'22.6"N 132°49'38.3"W	30/03
17382 15th Ed Mar 01 2003 Last LNM: 29/03 AK-SOUTHEAST COAST-ZAREMBO ISLAND AND APPR Relocate Coffman Cove Entrance Light FI W 2.5s 40ft 5M	NAD83 OACHES	(CGD17) at to	56°01'02.6"N 132°49'38.3"W 56°01'22.6"N 132°49'38.3"W	30/03
17401 10th Ed Sept 04 1999 Last LNM: 42/02 Add Coffman Cove Entrance Light FI W 2.5s 40ft 5M Add Coffman Cove Light 2 FI R 4s 32ft 3M Add Coffman Cove Lighted Buoy 3 FI G 6s Add Coffman Cove Lighted Buoy 4 FI R 2.5s	NAD83	(CGD17) at at at at	56°01'22.6"N 132°49'38.3"W 56°01'13.6"N 132°50'18.5"W 56°01'04.7"N 132°50'08.0"W 56°00'50.7"N 132°50'06.3"W	30/03

V ADVANCE NOTICE OF CHANGES TO AIDS TO NAVIGATION

NONE

VI PROPOSED CHANGES TO AIDS TO NAVIGATION

NONE

VII GENERAL

NONE

VIII LIGHT LIST CORRECTIONS

NONE

IX ADDITIONAL ENCLOSURES

S. Rothchild Aids to Navigation Branch Seventeenth Coast Guard District



Operational Excellence Through Leadership, Teamwork, And Continuous Improvement



Date 29 JULY 2003 PAGE 3